CALIFORNIA DEPARTMENT OF WATER RESOURCES

Assessment of Camp Fire Impacts to Lake Oroville





North Fork Feather River Canyon, Pre- and Post-Fire

Daniel Wisheropp & Calvin Yang

California Department of Water Resources Division of Operations and Maintenance Environmental Assessment Branch Camp Fire Water Resources Monitoring and Research Symposium June 4, 2019

Contents

- 1. Lake Oroville overview
- 2. Debris flow potential
- 3. Potential impacts to Lake Oroville


- 4. Storm water sampling plan
- 5. Preliminary sample results
- 6. Next steps
- 7. Questions



Lake Oroville & Fire Boundary

- SWP facility

 Managed by DWR
- Multiple beneficial uses
 - Recreation
 - Water storage and power generation
 - Source of local drinking water
 - Terrestrial and aquatic habitat



Debris Flow Potential


Large areas of the North Fork Feather River Watersheds were severely burned


Severely burned areas lead to larger runoff volumes

Large runoff volume may potentially cause debris flows, mudslides, & excess run-off

- Even small erosion sites have potential to produce large effects over time
- Burn area severity surveys and potential debris flow maps produced by USGS

Debris Flow Probability Maps





Potential Impacts to Lake Oroville


- Increased sediment and solids
- Increased metals and minerals
- Increased nutrients (potential algae blooms)
- Inflows of combustion related toxins (PAHs)
- Impacts to Lake Oroville 303d listed compounds

 Impaired for mercury and PCBs
 303d list is compiled by SWRCB

Sampling Locations


Very remote area with few roads. Safety, access, and representativeness were taken into account in site selection.

- 1 location upstream of the burned area
- 1 location upstream of Lake Oroville
- 2 locations in the upper arms of Lake Oroville (boat sites)



Sampling Dates

- Collected samples during or after heavy storms
 - Missed first flush event, occurred during the fire
 - First samples 12 days after 100% containment
 - Spread samples throughout Winter and into Spring
 - No sample in April, one sample in May (data pending)



Analytes and Methods

- Analyte list modeled after Carr Fire and other Camp Fire sampling plans

 Metals, nutrients, minerals, solids, PAHs, plus PCBs
- Collected with Van Dorn or steel bucket

 Dissolved samples filtered in field
 - Analyzed at DWR's Bryte Lab or TestAmerica Labs
- Physicals measured with YSI ProDSS








Preliminary North Fork Results

- Hwy 70 (upstream of the fire) vs.
 Poe PH (upstream of Lake Oroville)
 - Not affected by lake effects (next slide)
 - Largest, consistent increases shown below
 - Table shows average increase over all dates
 - Common soil-related parameters
 - Largest increases were in the first sample set
 No PCBs or PAHs detected


	Average	
Analyte	RPD	
T. Aluminum [#] +	319%	
T. Iron # +	124%	
T. Manganese [#] +	138%	
T. Nickel +	143%	


	Average
Analyte	RPD
D. Nitrate	78%
T. Phosphorus	188%
Total Suspended Solids	221%
Turbidity	327%

Some >MCL samples at both locations + Smaller increases and decreases for dissolved



Preliminary Lake Oroville Results





Influenced by low lake levels and re-suspension ulletof sediment already in the lake

900

850


750

700

650

- High results for soil-related parameters observed:
 - When the lake was low (December and January)
 - When rainfall was high (January and February)
- Lower concentrations for "totals" at higher lake levels.
- PAHs detected in March at both lake sites No detections in other months or at other sites


Preliminary North Fork Longitudinal Sample Analysis






Rain Total: Low

- Minor or small increase between upstream and Poe
- Large increase in "Total" analytes in the lake




Lake Level: Moderate Rain Total: Very High

- Larger increase in "Totals" between upstream and Poe
- Large increase in TSS in the lake
- Minor to small increase in total metals and dissolved analytes between Poe and the lake



- Minor or small increase between upstream and Poe
- Large increase in "Total" analytes in the lake



Lake Level: Very High Rain Total: Moderate

- Minor increase in TSS and total metals between upstream and Poe
- Minor or no increase other analytes
- Decrease in "Totals" between Poe and the lake
- **Hwy 70** 1.5 Miles 70 Poe PH North Fork Arm Lake Oroville

Preliminary Conclusions


- Likely a higher influx of concentrations for some analytes compared to those absent the fire
 - Especially solids, total metals, and nutrients
 - Primarily related to increased erosion
- More analysis needed for lake vs fire effects
 - Early lake samples were adversely affected by low lake levels (i.e., shallow depth at sample point)
 - Later samples showed increased dilution in the lake
- Effects to beneficial uses of Lake Oroville and the long term impacts need further analysis

Next Steps


- Finish assessing the late-2018 and early-2019 storm water effects on Lake Oroville
 - Incorporate pending May 2019 sample results
 - Further analyze re-sedimentation and dilution effects on lake samples
 - Possible post-rain season sampling in June
 - Evaluate long-term Lake Oroville sample data
- Based on final analysis and findings, determine if and/or how much further monitoring is needed next water year







Daniel Wisheropp Daniel.Wisheropp@water.ca.gov (916) 653-0955



<image>





Calvin Yang Calvin.Yang@water.ca.gov (916) 653-1154